



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEX Scheme visit www.iecex.com

QAR Ref. No.: **US/UL/QAR06.0010/09** Page 1 of 1

QAR Free Ref. No.: **4788905123** Status: **Issued**

Details of change: Reassessment Audit Date of issue: **2019-07-31**

Site(s) audited: Otto Engineering 2 East Main Street Carpentersville, IL 60110 USA Valid until: **2022-09-28**

Issuing ExCB: **UL - UL LLC** Audit date: **2019-07-17**

Manufacturer: **Otto Engineering**
2 East Main Street
Carpentersville, IL 60110

Location of Manufacturer: **United States of America**

Product information: Audio Accessories

Protection concept: **Intrinsically Safe "i"**

Related QARs:

US/UL/QAR06.0010/00	US/UL/QAR06.0010/01	US/UL/QAR06.0010/02
US/UL/QAR06.0010/03	US/UL/QAR06.0010/04	US/UL/QAR06.0010/05
US/UL/QAR06.0010/06	US/UL/QAR06.0010/07	US/UL/QAR06.0010/08

Related Certificates (manual insertion):

Related Certificates (automatic linking): [IECEX UL 06.0008X issue: 3](#)
[IECEX UL 20.0041 issue: 0](#)
[IECEX UL 09.0022X issue: 4](#)
[IECEX UL 19.0066 issue: 0](#)

Related Certificates for previous versions:

IECEX FMG 14.0030 issue: 0	IECEX FMG 14.0030 issue: 1	IECEX FMG 14.0030X issue: 2
IECEX FMG 14.0030X issue: 3	IECEX FMG 15.0018X issue: 0	IECEX FMG 15.0018X issue: 1
IECEX FMG 15.0018X issue: 2	IECEX UL 06.0008X issue: 1	IECEX UL 06.0008X issue: 2
IECEX UL 06.0009X issue: 1	IECEX UL 06.0009X issue: 2	IECEX UL 09.0022X issue: 0
IECEX UL 09.0022X issue: 1	IECEX UL 09.0022X issue: 2	IECEX UL 09.0022X issue: 3

Comments: